



Sanitary Landfill Wastes (placed)




Sanitary Landfill Liner/Cover



Sanitary Landfill Berm (fill)



Cut material during construction




Existing Wastes removed



Existing Wastes left in place

Drawing from December 1992 showing the overflow pond and site conditions by Monsanto Research Corporation

Horizontal and Vertical Scale



1976 plans for construction of
site sanitary landfill, prepared
corporation

Scale - 1" = 20' (1:240)